

#### Features

- Measures ambient temperature and relative humidity
- Designed for one-handed operation
- Backlit dual LCD display
- User selectable °F/°C
- Max, min and data hold functions
- Low battery indicator and auto shut off
- Includes batteries

#### Specifications

##### Temperature

Measuring Range: 14 to 140°F (-10 to 60°C)  
 Accuracy: ±2.0°F (1.0°C)  
 Resolution: 0.1°F/°C

##### Humidity

Measuring Range: 0 to 100% RH  
 Accuracy: ±5% RH  
 Resolution: 0.1% RH

##### General Specifications

Display: Dual LCD  
 Backlit Display: Yes  
 Data Hold: Yes  
 Max: Yes  
 Min: Yes  
 Sampling Rate: 1 time/sec.  
 Overrange Indicator: Yes  
 Auto Shut-off: Yes (after 5 mins, off)  
 Low Battery Indicator: Yes  
 Power Supply: 3 AAA Batteries  
 Product Certifications: CE  
 Operating Temperature: 32 to 122°F (0 to 50°C)  
 Storage Temperature: 14 to 140°F (-10 to 60°C)  
 Operating Humidity Range: 10 to 80%  
 Dimensions: 6.3 x 2 x 1.1"  
 (155 x 50 x 28mm)  
 Weight: 4.2 oz (102g)



Model	Description
R1910	Temperature & Humidity Meter
CA-52A	Soft Carrying Case